



Roofing Shingle Identification Report

Report # 5016820

Customer Details

Customer: **The Dude Abides Roofing, LLC**
Sample Received Date:
Order Date: 12/10/2023

Property Owner Details

Property Owner: Walter Sobchak Property Address: 123 Main Street, Fort Worth, TX 76244	Insurance Company: [REDACTED] Claim Number: [REDACTED] Roof Type: Residential Roof Size (Sq.Ft.): 5,000.00
---	---

Existing Roofing Surface Identification	✓ Positive Identification Confirmed ✓
Manufacturer: [REDACTED] Product: [REDACTED] Type: 3 Tab	Discontinued: Yes Currently in Production: No Compatible with Current Products: No

Product Notes: The sample product is discontinued. No manufacturer produces 20 year shingles that are 3 tab style strip shingles. The sample product is not to be mixed with the current 3 tab style strip shingles from GAF.

Additional Details:

Please Note: Supporting documentation should be reviewed in addition to this report

NTSID LLC - 3800 Haslet-Roanoke Rd Roanoke, TX 76262 Unit 4 - www.ntsidi.com
Page 1 of 2



Positive Identification

Your roofing product is modified, not to be mixed, or no longer in production.

Roofing Product Specifications

Manufacturer: [REDACTED]	Width: [REDACTED] Inches
Product: [REDACTED]	Height: [REDACTED] Inches
	Exposure: [REDACTED]
	Warranty: 20

Similar Roofing Product:

Additional Details: A sample of the roofing surface was analyzed; not the full roof assembly or system. Installers and owners should check current codes, local building requirements, manufacturers published documents, and any installation instructions before purchasing or installing products. Local requirements, statutes, ordinances, and guidelines should be checked to confirm any requirements for matching, uniform construction, appearance retention, or historical requirements.

✓ NTSID Positive Identification ✓

NTSID performed a complete multipoint inspection of the provided sample/images and determined the sample product type, manufacturer and brand. For additional questions please email us at info@ntsid.com

Shingle Images

Photo Front



Photo Rear

in the industry





We
protect
what
matters
most™

January 24, 2020

Technical Support Services

1 Campus Drive

Parsippany, NJ 07054

Phone: 1-800-766-3411

Subject: Do Not Mix - GAF Royal Sovereign® Shingles

To Whom It May Concern:

It is our understanding that you are inquiring about mixing current manufactured GAF Royal Sovereign® shingles with Royal Sovereign® shingles manufactured from the past on the same roof plane.

This is to confirm that GAF currently manufactured shingles must not be mixed with those manufactured in the past due to changes in sizes, manufacturing, color, and granule sourcing.

If you have any further questions, please contact us at 1-800-766-3411.

Sincerely,

Brittany Castillo

Brittany Castillo
Technical Support Services Representative

Do Not Mix 1/24/2020 BC



*“Quality You Can Trust Since 1886...From
North America’s Largest Roofing
Manufacturer”*

Technical Services
1 Campus Drive
Parsippany, NJ 07054
Phone: 1-800-766-3411

October 5, 2017

Subject: Do not mix

To Whom It May Concern:

This is to confirm that it is not recommended to mix currently manufactured shingles with those manufactured in the past as granule sourcing and manufacturing changes have occurred.

If you have any further questions, please contact us at 800-766-3411.

Sincerely,

Erica Lee

Erica Lee
Technical Services Representative

Technical Advisory Bulletin



We
protect
what
matters
most™

*What Are The
Underlayment
Requirements For
Hips When Only
Replacing A Single
Roof Plane?*

To: GAF Residential Sales, GAF Contractors, Field Services, AIS, CARE
From: Technical Services
No: TAB-R-164

Roof Repair Underlayment Requirements For Hips And Ridges

For hips, the underlayment should ... be lapped over the hips at least 4" (102 mm) to 6" (152 mm) as would be done on a new or complete tear-off installation. Follow the general instructions below:

- End nails of each course of shingles that are being left on the adjacent roof plane must be removed so that the underlayment may be inserted between the shingles and existing underlayment.
- Use a 12" (305 mm) to 18" (457 mm) strip of underlayment to run along the hip and overlap the new underlayment on the replacement plane at least 6" (152 mm) to 12" (305 mm).
- Once complete, the existing shingles must be re-nailed, hand sealed, and then the new hip cap can be installed. If any existing shingles are damaged, they must be replaced with new shingles.

Note: If the hip includes a hip vent, then the new underlayment must be trimmed to the edge of the vent slots so it will not interfere with air movement.

For ridges, the underlayment should ... be lapped over the ridge at least 4" (102 mm) to 6" (152 mm) as would be done on a new or complete tear-off installation. Follow the general instructions below:

- Nails of the top course of shingles that are being left on the adjacent roof plane may need to be removed so that the underlayment may be inserted between the shingles and existing underlayment.
- Use a 12" (305 mm) to 18" (457 mm) strip of underlayment to run along the ridge and overlap the new underlayment on the replacement plane at least 6" (152 mm) to 12" (305 mm).
- Once complete, the existing shingles must be re-nailed, hand sealed, and then the new hip cap can be installed. If any existing shingles are damaged, they must be replaced with new shingles.

Note: If the ridge includes a ridge vent, then the new underlayment must be trimmed to the edge of the vent slots so as not to block the venting.

*Will Reusing
Existing Materials
Or Not Following
These Instructions
Void My Shingle
Limited Warranty?*

Questions?

No... The GAF Shingle & Accessory Limited Warranty will remain in effect per its terms and conditions, however, any damage due to reusing existing shingles, ridge cap, under-layments or leak barriers are not covered under the terms of the limited warranty. The GAF Shingle & Accessory Limited Warranty covers manufacturing defects only; it does not cover the workmanship of the roofer who installs the shingles, the design of the roof, or the installation/performance of the roof deck. GAF makes no representation or warranty that the installation conforms to local code requirements and assumes no responsibility for code compliance.

GAF Technical Services Can Assist You... with these and other questions you may have regarding your new roof installation. Technical Support Services can be contacted at 800-766-3411. The GAF website is a great resource for just about any question you may have or for additional information you may require. Please visit www.gaf.com to find the latest information on our products and their installation.

Important: This document supersedes any prior GAF Technical Advisory Bulletins on this topic. Please always check www.gaf.com to make sure you have the most up to date information.